

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, ILLINOIS 60604

**SUBJECT:** CLEAN AIR ACT INSPECTION REPORT

Citgo Holdings Terminal, LLC, East Chicago, IN

**FROM:** Meaghan Pashen, Environmental Engineer

AECAB (MN/OH)

**THRU:** Brian Dickens, Section Supervisor

AECAB (MN/OH)

**TO:** File

### **BASIC INFORMATION**

Facility Name: Citgo Holdings Terminal, LLC – East Chicago Terminal

Facility Location: 2500 East Chicago Avenue, East Chicago, IN 46312

**Date of Inspection:** August 2, 2022

#### **EPA Inspector(s):**

- 1. Meaghan Pashen, Environmental Engineer
- 2. Jason Schenandoah, Environmental Engineer

#### **Other Attendees:**

- 1. Maher Saad, Terminal Manager
- 2. Eric Rajski, Assistant Terminal Manager
- 3. Sasa Dunovic, IDEM Inspector

Contact Email Address: msaad@citgo.com

**Purpose of Inspection:** To determine facility compliance with the New Source Performance Standard (NSPS) Subpart Kb – Standards of Performance for Volatile Organic Liquid (VOL) Storage Vessels (40 C.F.R. Part 60, Subpart Kb) with respect to petroleum product storage tanks.

**Facility Type:** Bulk petroleum product storage and transfer terminal

**Regulations Central to Inspection:** NSPS Subpart Kb – Standards of Performance for VOL Storage Vessels, including the obligation to perform preventative maintenance to ensure storage

tank control equipment performance, and to ensure storage tanks are equipped with a closed vent system designed to collect all VOL vapors and gases discharged from the storage tank.

**Arrival Time:** 1:00 PM **Departure Time:** 2:45 PM

### **Inspection Type:**

☑ Unannounced Inspection☑ Announced Inspection

### **OPENING CONFERENCE**

	Credentials
--	-------------

- Stated authority and purpose of inspection

The following information was obtained verbally from Maher Saad or Eric Rajski unless otherwise noted.

### **Process Description:**

Citgo's East Chicago Terminal (the Facility) consists of 53 tanks to store various petroleum and related products, including: gasoline, gasoline blending agents, diesel, jet fuel, biodiesel, ethanol, butane, trans mix, and distillate products. Movement of product into and out of the Facility occurs primarily via bi-directional pipelines, except for distillate product which may be moved into and out of the Facility via trucks at a 2-bay loading rack. Gasoline storage tanks have fixed roofs and use internal floating roofs to control vapors.

**Staff Interview:** The terminal does not have a loading rack for gasoline. The loading rack for distillate has no vapor combustion unit (VCU) or vapor destruction unit (VDU) and associated emissions are vented to the atmosphere. Among the various tanks at the Facility, Tanks 7, 38, 39, and 43 contain gasoline. The design capacity of Tanks 7, 38, 39, and 43 is greater than 151 m<sup>3</sup> for each tank, and each of the tanks are subject to requirements under NSPS Subpart Kb.

NSPS Subpart Kb requires the performance of preventative maintenance on storage tanks and associated control equipment. Facility staff performs monthly visual inspections of the tanks and roofs which consist of visual and odor checks. Facility staff did not indicate any instance of vent leaks identified during these inspections. Annual visual inspections are conducted on the secondary seals of each floating roof. Out of service seal inspections are conducted every 10 years and API-653 inspections are conducted concurrent with them. EPA requested these inspection reports and associated repair memos for Tanks 7, 38, 39, and 43.

### **TOUR INFORMATION**

**EPA Tour of the Facility:** Yes

### **Data Collected and Observations:**

EPA observed and recorded several videos indicating hydrocarbon emissions from vents located at the tops of Tanks 7, 38, 39, and 43 using a Forward Looking InfraRed (FLIR) camera. See Digital Image Log.

**Photos and/or Videos:** were taken during the inspection.

See Appendix A: Digital Image Log

Field Measurements: were not taken during this inspection.

### **CLOSING CONFERENCE**

□ Provided U.S. EPA point of contact to the facility

### **Requested documents:**

- For Tanks 7, 38, 39, and 43:
  - o Last five annual visual inspection reports;
  - o Last out-of-service inspection reports, including API reports; and
  - Associated repair memos for all inspections listed above.

**Concerns:** EPA informed facility staff that the emissions observed at Tanks 7, 38, 39, and 43 may need further investigation.

### **DIGITAL SIGNATURES**

Report Author:	 	
Section Supervisor:		

**Facility Name:** Citgo Holdings Terminal, LLC – East Chicago Terminal **Facility Location:** 2500 East Chicago Avenue, East Chicago, IN 46312

**Date of Inspection:** August 2, 2022

# APPENDICES AND ATTACHMENTS

1. Appendix A: Digital Image Log

**Facility Name:** Citgo Holdings Terminal, LLC – East Chicago Terminal **Facility Location:** 2500 East Chicago Avenue, East Chicago, IN 46312

**Date of Inspection:** August 2, 2022

# **APPENDIX A: DIGITAL IMAGE LOG**

1. Inspector Name: Jason	2. Archival Record Location: R5 Electronic Records
Schenandoah	Center: Citgo East Chicago File

Image Number	File Name	Date and Time (incl. Time zone and DST)	Latitude and Longitude	Description of Image
1	MOV_0452.mp4	August 2, 2022 9:35 am		Emissions from vents and top of Tank 38
2	MOV_0453.mp4	August 2, 2022 9:40 am		Emissions from vent of Tank 39
3	MOV_0454.mp4	August 2, 2022 9:42 am		Trailing vapors from Tank 39
4	MOV_0455.mp4	August 2, 2022 9:47 am		Emissions from vent of Tank 39
5	MOV_0456.mp4	August 2, 2022 9:49 am		Emissions from vent of Tank 43
6	MOV_0457.mp4	August 2, 2022 9:50 am		Emissions from vent of Tank 43
7	MOV_0458.mp4	August 2, 2022 9:52 am		Emissions from unknown tank
8	MOV_0459.mp4	August 2, 2022 10:01 am		Emissions from vents of east side of Tank 7
9	MOV_0460.mp4	August 2, 2022 10:04 am		Tank 3 and view towards neighboring property
10	MOV_0461.mp4	August 2, 2022 10:06 am		Emissions from vents of west side of Tank 7